

SS SERIES - Scotch yoke / Spring return 拔叉式/ 单动


Part List




Operating Mechanism



Fail Open





un		

Dimension Table								
Ball Valve (10k)								
SS50	15A ~ 25A							
SS65	25A ~ 40A							
SS80	50A ~ 65A							
SS100	80A							
SS125	100A							
SS140	125A							
SS160	150A							
SS210	200A							

_														umiiim	
	MODEL	ISO	L	Т	T1	Н	H1	K	K1	CH	P.C.D (Ø)	N-M	DEPTH	WG(Kg)	
	SS50	F03/F05/F07	258	69	40	87	67	11	80	11 x 11	36/50/70	4-M5/M6/M8	13	1,6	
	3330	F03/F03/F0 <i>1</i>	230	09	40	01	01	- 11	00	9,7 x ø15	30/30/70	4-1013/1010/1016	14		
										14 x 14			17		
	SS65	F05/F07	320	83	46	106	86	13	80	11.7 x Ø17	50/70	4-M6/M8	17	3,2	
										9.7 x Ø15			15		
	SS80	F07	418	98	54	122,5	103	15	80	17 x 17	70	70	4 MO	19	E /
	3300	FU/	410	90	34	122,3	103	13	00	14.7 x ø19.5	70	4-M8	20	5.4	
										22 x 22			26		
	SS100	F07/F10	506	116.5	61.5	143	122.5	22	80	19.7 x Ø28	70/102	4-M8/M10	27	10	
										17.7 x Ø22			27		
	SS125	F07/F10	620	137	60.5	168	148	22	80	22 x 22	70/102	4-M8/M10	26	17	
										27 x 27					
	SS140	F10/F12	716	154	77	190	170	22	80	22 x 22	102/125	4-M10/M12	30	24	
										19 x 19					
	00160	F14	015	178	88	010	100	32 80	00	36 × 36	140	4-M16	00	35	
	SS160	F10/F12	815	170	00	210	190		60	27 × 27	102/125	4-M10/M12	30		
	00010	F16	980	000	110	290	061	36	130	46 x 46	165	4-M20	60	70.5	
	SS210	F16	900	230	112	290	261	30	130	36 × 36	100		50	72.5	

Selection Guide

Torque Table								
Butterfly Valve (10k)								
SS50	40A ~ 50A							
SS65	65A ~ 80A							
SS80	100A ~ 125A							
SS100	150A ~ 200A							
SS125	250A							
SS140	300A							
SS160	350A ~ 400A							
SS210	450A							
Selection Guide								

							unit:Nm				
		SPRING TORQUE									
MODEL	ANGLE	We	eak	Mic	ldle	Strong					
		Spring to Close	Air to Open:3Bar	Spring to Close	Air to Open:4.5Bar	Spring to Close	Air to Open:6Bar				
	0 °	10,0	20,0	14.0	26,0	17,0	34.0				
SS50	45 °	9.0	9,0	12,0	12,0	15.0	15,0				
	90 °	20,0	10,0	26.0	14.0	34,0	17,0				
	0 °	22,0	39,0	35,0	54.0	48,0	70,0				
SS65	45 °	18.0	18,0	23,0	28,0	37,0	32,0				
	90 °	39,0	22,0	54 <u>.</u> 0	35,0	70,0	48,0				
	0 °	40,0	70,0	60,0	100,0	80,0	130,0				
SS80	45 °	30,0	30,0	50,0	50,0	70,0	70,0				
	90 °	70,0	40,0	100,0	60,0	130,0	80,0				
	0 °	70,0	140,0	100,0	190,0	130,0	240,0				
SS100	45 °	50,0	50,0	80,0	80,0	110,0	110,0				
	90 °	140,0	70,0	190,0	100,0	240,0	130,0				
	0 °	150,0	250,0	230,0	380,0	300,0	510 <u>.</u> 0				
SS125	45 °	130,0	130,0	190,0	190,0	260,0	260,0				
	90 °	250,0	150,0	380,0	230,0	510,0	300,0				
	0 °	200,0	370,0	300,0	550,0	410,0	730,0				
SS140	45 °	170,0	170,0	290,0	290,0	340,0	340,0				
	90 °	370,0	200,0	550,0	300,0	730,0	410,0				
SS160	0 °	400,0	540,0	550,0	750,0	769,9	1149.9				
	45 °	290,0	290,0	420.0	420,0	560,0	560,0				
	90 °	540,0	400,0	750.0	550,0	1149.9	769,9				
	0 °	670,0	1199,9	1049,9	1619.9	1419.9	2169.9				
SS210	45 °	560,0	560,0	939,9	939,9	1259 _. 9	1259.9				
	90 °	1199 <u>.</u> 9	670,0	1619 <u>.</u> 9	1049.9	2169 <u>.</u> 9	1419 <u>.</u> 9				